## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20210556Address:326 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspectio	on:	Inspector:	Outcome:	Date:
Sidewall	Inspection	Eric Sharp	Failed	Friday, November 19, 2021
Informational: 1 Misc		Sidowalk is framed up wi	th aggregate in and compare	tod 11/12 ES
L Correctiv	e Action Required:	Sidewalk is framed up with aggregate in and compacted. 11/12 ES		
2	Misc	Sidewalk meets LS and Ada spec. However, sidewalk has multiple panels that need replaced due to chipping or damage all panels marked with pink X need replaced. 11/19 ES		

**Comments:**