JLL Architecture, LLC 200 East Randolph Drive Chicago Illinois 60601 51 W 3rd Street, Suite 201, Tempe, AZ 85281 tel +1 480 626 6304 fax +1 480 401 3602

November 23, 2021

The City of Lee's Summit, Missouri Development Services/ Fire Department

220 SE Green Street Lee's Summit, MO 64063

Phone: (816) 969-1200 / (816) 969-1300

Re: Change of Tenant- LensCrafters

PRCOM20215330

Project Address: 1700 NW Chipman RD

Dear Mr. Joe Frogge

This letter contains our responses to the review comments received for the above project. Please also refer to our enclosed revised documents.

Our revisions have been clouded and tagged as:

Revision Delta #1, 'City Comments', Date: 10/22/2021

Licensed Contractors: (Joe Frogge)

The General Contractor identified for this project will adhere to Code of Ordinance Section 7-130.10 and submit their Class A or B Business License. Providing the name of the licensed general contractor and an email address for the on-site contact.

MEP subcontractors are required to be listed on permit.

Building Plan Review: (Joe Frogge)

All references are to the 2018 International Building Code unless noted otherwise

Please refer to corrections and comments noted on revised documents and listed below.

- 1. G001:
 - a. Construction Type is II-B, as per Table 601 of the 2018 IBC.
- 2. A103:
 - a. Reference keynote #9 for additional information and FRP-2 on sheet G008.

New HVAC units are to be installed and included with the Landlords work and drawings. They are shown for reference and duct connection.

Fire Plan Review: (Michael Weissenbach)

All references are to the 2018 International Fire Code unless noted otherwise

- 3. FP200:
 - a. Shown for design reference only, registered Engineer will be required to comply with all local codes.

Change of Tenant PRCOM20215330. Lens Crafters, 1700NW Chipman RD, Lee's Summit, MO

Revision Delta #2, 'Owner Revisions', Date: 10/29/2021

- 1. G007a:
 - a. Owner updated entire sheet to help clarify door conditions
- 2. G007b:
 - a. Owner updated entire sheet to help clarify glazing conditions
- G009:
 - a. Sliding door at room 102 Contacts has been modified to allow for accessible clearances.
- 4. A100:
 - **a.** Sliding door at room 102 Contacts has been modified to allow for accessible clearances.
- 5. A101:
 - a. Sliding door at room 102 Contacts has been modified to allow for accessible clearances.
- A102:
 - a. Sliding door at room 102 Contacts has been modified to allow for accessible clearances.
- 7. A103:
 - **a.** Sliding door at room 102 Contacts has been modified to allow for accessible clearances.
- 8. A104:
 - **a.** Sliding door at room 102 Contacts has been modified to allow for accessible clearances.
- 9. A200:
 - **a.** Sliding door at room 102 Contacts has been modified to allow for accessible clearances on elevation 4 and 8.
- 10. A201:
 - **a.** Door symbols have been updated to coordinate with sheet G007a.
- 11. A202:
 - **a.** Door symbols have been updated to coordinate with sheet G007a.
- 12. A203:
 - **a.** Interior elevations have been updated to coordinate with sheet A103.

Thank you,



Amy Sjursen, AIA, NCARB Architect

Director, Architecture, Architect of Record

Phone: (718) 887-1220 Amy.Sjursen@am.jll.com Jon H. Morton, CM. CSBA, Assoc. AIA

Project Manager Phone: (480) 277-4030

Jon.Morton@am.jll.com