CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211858

Address: 111 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Tuesday, December 07,

Residential 2021

Corrective Action Required:

1 Miscellaneous : PFH PORTAL FRAME ONLY :

Correction - 5/8 ANCHOR BOLTS SHALL BE IN MIDDLE 1/3 THE WIDTH OF PLATE -

CHECK ABOVE ON ALL ROUGH

OK TO COVER EXTERIOR AT PFH PORTAL

Corrective Action Required:

2 Miscellaneous Seal fire blocking dead space at entry closet

Correction Provide fire blocking landing at entry NW corner

Seal Nm conductors in plenums kitchen

Seal upward penetration at HVAC chase mud room near joist hanger

Seal fire blocking above refrigerator

Provide 3 studs under triple LVL garage behind range

Fire block radon furr out rear garage wall

5/8 anchor bolts at PFH portal frame shall land in middle 1/3 the width of plate

Anchor bolts garage shall land in middle 1/3 the width of plate Provide anchor bolt end of plate garage near entry closet

Address cut joist pantry

Seal fire blocking chases great room Seal fire blocking above fireplace Seal top plate penetration bed 1 closet

Strap top plate bed 1 closet Nail stud shoe master vanity Provide boca plate laundry room Nail exterior wall sheathing per code

Comments: