

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20214989, Public Works Right of Way Permit
Address: 210 NW PRYOR RD, Unit:ES, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Nick Scott	Partial	Tuesday, December 07, 2021

Corrective Action Required

1	Misc	Contractor cut into one sidewalk panel. There are several piles of dirt that need to be removed. Matt M has contacted the contractor about putting sidewalk back per city standards.
---	------	--

Corrective Action Required

2	Misc	Crews are onsite and working. The concrete will be poured on Thursday 10/7. They are going to fill the hole flush with AB-3 until the concrete is poured. Nick Scott spoke with the crew about city specs.
---	------	--

Corrective Action Required

3	Misc	Site visited no one was on the job site the pad had been torn out with no fence or cones around it. I will contact Teague electric. And then at the end of the day I will come by and check it again.
---	------	---

Corrective Action Required

4	Misc	Site visited. Still no cones or fenced. I left a voicemail with Matt Hull the foreman 913-238-6020 waiting for a call back. Will be back before the end of the day to check up on it again.
---	------	---

Corrective Action Required

5	Misc	Site visited at 3 45 and Teague electric still hasn't put out cones or fence. We called them and talked to the guy a head of Matt Hull and his name is Jared and told him that he need to get something around the hole in between the concrete pads. Then Matt M called Summit homes and talked to Travis Ruff 816-564-9088 and we asked him to get some cones out around the hole. Travis said he would personally go out and get some safety tape and cones. I will go back out there first thing tomorrow and check.
---	------	--

Corrective Action Required

6	Misc	Site Visited No crew is working dirt is still piled up. All pits are
---	------	--

filled in I will give them one more week before I start calling Teague electric to see what is going on with the piles of dirt and restoration of grass.

Corrective Action Required

7 Misc

Site visited and piles of dirt is still on job site and no restoration has been done. I called Travis Ruff and left a message trying to figure what is going to be done.

Corrective Action Required

8 Misc

Site visited and it appears that restoration is halfway complete. I will check this springs if it has not been finished.

Comments: