CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210729 Address: 2159 NW KILLARNEY LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector: Michael Harkins	Outcome:	Date:	
			Failed	Monday, December 27, 2021	
Correct	tive Action Required:				
1	Miscellaneous	Tighten anchor bolts basement			
	Correction	Provide anchor bolt end of plate near service panel			
		Provide washer anchor bolt near wall out door basement			
		Insulate & solid block cantilever above basement windows			
		Nail both sides (4) 2x10 joist above SCH 40			
		Column basement			
		Nail triple LVL from both sides between furnace & SCH 40 column			
		Address joist notched for plumbing at east cantilever			
		Address double 2x10 joist bed #2 plans show double 2x12			
		Protect exhaust duct & seal upward penetrations bed # 3			
		Provide (3) 2x4 entry coat closet per plan			
		Provide LIB near refrige	erator per plan		
		Provide (2) 2x10 joist p	er plan mud room		
		Seal fire blocking dead space powder room/HVAC chase			
		Provide (3) 2x4 under L	.VL pantry per plan		
		Seal bottom plate penetrations pantry			
		Provide stud shoes DW	'V pantry		
		Expose covered patio c	eiling joist (3) 2x12 per	plan	
		Provide (3) 2x12s flush	per plan owners suite		
		No roof load on wall be	etween owners suite &	master bath per plan	
		Provide (3) 2x4 owners	closet per plan		

Fire block ceiling line flex room Provide (2) 2x4 closet dead space flex room per plan Provide (2) 2x4 under 2x12 @ entry per plan Provide (5) 2x4 under beam at single car door per plan Provide (3) 2x4 under LVL garage/pantry per plan Provide (3) 2x10 joist per plan garage/ mech chase Tighten 5/8 anchor bolts PFH portal frame garage Tighten anchor bolts garage Furr out DWV at garage beam PFH portal frame panel splice shall occur within 24" of mid height per detail 1 sheet S4.0 Unable to verify 3" nailing pattern header PFH portal framing Nail exterior wall sheathing per code Seal upward penetration gas line deck fireplace Fireplace on covered deck not on city approved plans

Comments: