## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRSUBD20212196

Address: 1630 NE WOODS CHAPEL RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspectio                   | n:                    | Inspector:                                                                                                                                                                                                                                                                                                                | Outcome:                   | Date:                           |
|-----------------------------|-----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|---------------------------------|
| Storm Ser<br>Inspectio      | wer Construction<br>n | Adam Nacke                                                                                                                                                                                                                                                                                                                | Partial                    | Wednesday,<br>December 29, 2021 |
| Corrective Action Required: |                       |                                                                                                                                                                                                                                                                                                                           |                            |                                 |
| 1                           | Misc                  | 10-25-21 AN There are 12 storm boxes that were all place at the wrong elevation and had to be cut down or shimmed up. Most of them were placed 3in to high give or take. I spoke with James at Holthouse about how they were going to be fixed and told him not to back fill around the boxes until they are reinspected. |                            |                                 |
| Informational:              |                       |                                                                                                                                                                                                                                                                                                                           |                            |                                 |
| 2                           | Misc                  | 12-29-21 AN crew has bee lids                                                                                                                                                                                                                                                                                             | n working on repairing the | gaps on the storm boxes         |

## **Comments:**