



# LEE'S SUMMIT MISSOURI



## FIRE DEPARTMENT

### NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	PETPEOPLE		
ADDRESS	940 NW PRYOR RD, Unit:J, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	PYCIOR & CO:	TELEPHONE	(816) 564-7791
ADDRESS	302 NE DOUGLAS ST LEES SUMMIT, MO 64063 Primary: (816) 564-7791 Cell: (816) 564-7791		

### EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	
2. _____	
3. _____	
4. _____	

### LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: M	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

### LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Craig Hill	Failed	Monday, January 10, 2022
Corrective Action Required:			
1 Label north west door. "No exit door blocked" and "door blocked".			
Address main front door.			
Address back door to hallway.			
Fix fire alarm reporting.			

<b>Sprinkler - Hydrostatic Test</b>	Craig Hill	Not Required	Monday, January 10, 2022
-------------------------------------	------------	--------------	--------------------------

<b>Sprinkler - Flow Test</b>	Craig Hill	Not Required	Monday, January 10, 2022
------------------------------	------------	--------------	--------------------------

<b>Occupancy Inspection - Fire</b>	Craig Hill	Failed	Monday, January 10, 2022
------------------------------------	------------	--------	--------------------------

Corrective Action Required:

- 1      Label north west door. "No exit door blocked" and "door blocked".  
Address main front door.  
Address back door to hallway.  
Fix fire alarm reporting.

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
----------------	-----------	-----------------------------------	-----------------------

January 10, 2022

INSPECTOR

Craig Hill

PREVENTION FOLLOW-UP  
REQUIRED?

☐ Yes    ☐ No

RESPONSIBLE SIGNATURE