CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211709

Address: 2357 SW OLD PORT RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Tuesday, January 18,

Residential 2022

Corrective Action Required:

1 Misc -Boca plate protection for dwv in basement to extend 2" above bottom plate

-anchor bolts within 12" of plate breaks

-provide 1 1/2" bearing on bottom of rafter at sheathed valley

-provide 75% bearing at hip to wall connection

-remove roof support to ceiling joist in garage, move to bearing wall (ridge

and hip above garage entry door) -provide collar ties per code

-fire stop garage to stairway dead space

-address roof lid landing on ceiling joist over laundry/pantry

-strap top plate breaks rear garage wall where breaks less that 24" apart

-solid block cripple wall above great room/kitchen

-strap top plate with rear family room and dining room meet

-address thermostat wiring in return air-uncover covered deck for inspection

-provide (2) 1/2" through bolts at deck post to beam connections

-provide supposed for furr down joist

-address over notched studs west basement wall

-seal penetrations in vertical to horizontal fire blocking

-vertical to horizontal fire blocking every 10' see sw wall

-provide fire blocking at furred down ends and beam ends in basement

-basement bearing wall add header and stud where top plates cut

- -provide protection for ward flex above basement stairs
- -provide stud pack per plans
- -provide 3" bearing on lvl to exterior wall bearing to basement floor

Comments: