



LEE'S SUMMIT MISSOURI



FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	KIDS 2 LEADERS MARTIAL ARTS		
ADDRESS	821 SW LEMANS LN, LEES SUMMIT, MO 64082		
OWNER/OPERATOR NAME	Longbow Contracting:	TELEPHONE	(816) 352-9271
ADDRESS	914 SW GEORGETOWN DR LEES SUMMIT, MO 64082 Primary: (816) 352-9271 Cell: <NO CELL PHONE>		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	
2. _____	
3. _____	
4. _____	

LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: A-4	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Craig Hill	Not Required	Thursday, January 13, 2022
Sprinkler - Hydrostatic Test	Craig Hill	Not Required	Thursday, January 13, 2022
Sprinkler - Flow Test	Craig Hill	Not Required	Thursday, January 13, 2022

Occupancy Inspection - Fire Craig Hill Failed Wednesday, January 19, 2022

Corrective Action Required:

- 1 Add exit sign to West door.
Change duck detection to come in as a supervisory and not a general alarm.
Fire sprinkler system is out of date by almost two years.
Add fire extinguisher to back hall.

Occupancy Inspection - Fire Craig Hill Passed Thursday, January 20, 2022

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
January 20, 2022	Craig Hill	<input type="checkbox"/> Yes <input type="checkbox"/> No	