CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210252

Address: 138 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy Inspection - Codes Robb Popp Failed Friday, January 21,

Residential 2022

Corrective Action Required:

1 Misc - SUMBIT ENGINEERS SOIL REPORT & REPORT ON

8" LIFT COMPACTION ON AB-3 PER FOOTING INSPECTION

Corrective Action Required:

2 Misc 1-21-22

HOUSE NOT READY FOR OCCUPANCY INSPECTION, CORRECT THESE ITEMS

BEFORE RE SCHEDULING

-PROVIDE EROSION CONTROL AT PERIMETER AND CLEAN DEBRIS FROM

STREET

- SUMBIT ENGINEERS SOIL REPORT & REPORT ON

8" LIFT COMPACTION ON AB-3 PER FOOTING INSPECTION

-PROVIDE SECURITY LIGHTING AT FRONT PORCH

-COMPLETE ALL TRADES INSIDE

Comments: