

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20215017  
Address: 126 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Erosion Control</b>	Robb Popp	Failed	Friday, January 21, 2022

Corrective Action Required:

1	DCM2 ESC DEFICIENT INSTALLATION	1-21-22  DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. -MAINTAIN SILT FENCE AT FRONT OF LOT, CLEAN DEBRIS FROM STREET, CLEAN DEBRIS FROM STORM INLET AND REPLACE GUTTER BUDDY
---	---------------------------------------	--

**Comments:**