CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRESRES20204862

Address: 330 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Shawn Hoffman Failed Tuesday, January 25,

Residential 2022

Corrective Action Required:

2 Miscellaneous

Correction - Label non GFCI outlet in garage

- Provide spark rings outlets kitchen counterGfci outlet over bar counter will not reset
- Outlets at bar need spark ringsLabel non GFCI outlets in basement
- Smoke detector by furnace covered and beeping
- Provide 6" clearance grade to siding garage by front door sidewalk
 Provide 2 x 1/2" through bolts on all post to beam connections
- complete irrigation permit and submit backflow cert.

Comments: