CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204939

Address: 2115 NW KILLARNEY LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Not Ready Tuesday, February 22,

Residential 2022

Corrective Action Required:

1 Miscellaneous Tighten anchor bolts basement

Correction Anchor bolts shall land in middle 1/3 the width of plate

Provide anchor bolt end of plate near patio door

Fire blocking above ufer Provide ufer access panel

Provide anchor bolts SCH 40 column unfinished

Provide exhaust fan basement baths Fire block soffit at stairway & hallway

Seal upward penetrations Jack n Jill bath pex at vanity

Address Joist NM bored within 2" of the edge rear bedroom closet

Nail exterior wall sheathing per code

Land conductors in a box

Where ceiling are not installed connected to to the rafters at the top plate rafter ties shall be installed in lower 1/3 of attic space per plan framing note #7

Tighten anchor bolts garage

Seal bores in cavities used as plenum near fire place & bed 2

Seal bottom plate penetrations office Complete fireplace vent to roof

Secure fireplace

Expose covered patio for inspection

Provide LIBs per plan

Seal bottom plate penetrations powder room near bed 2
Provide PFH portal framing garage per plan detail A 1
Provide 3 x 11 1/4 header CS-PF portal frame at breakfast nook per plan detail A4 (2018 IRC figure R602.10.6.4)
Complete plumbing at hole in floor powder room
Provide double joist below master bath per plan bar area
Provide double joist per plan bed 3
Install back ordered doors & windows
PROVIDE BOND ON gas line (CSST)
0 PSI ON GAS GUAGE
SEAL UPWARD PENETRATION REAR BEDROOM CLOSET

: 2/22/22

INSULATED WITHOUT APPROVAL REMOVE INSULATION FOR RE INSPECTION ENGINEER TO ADDRESS NOTCHED LVL HEADER AT BASEMENT PATIO DOOR

Comments: