## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20213818

Address: 4720 NE FREEHOLD DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Khanh Nguyen Not Ready Friday, February 25,

Residential 2022

## Corrective Action Required:

1 Misc

- -Deck beam not double 2x12 as shown on plan. Deck posts are required to be notched for beam attachment with two 1/2" through bolts or equivalent.

  \*\*Install two 1/2" through bolts or equivalent at each beam-post connection

  \*\*The posts are not notched the whole depth of the deck beam. Get your engineer to address/ok this
- -Have engineer address size of beam above great room slide door. Plan shows multiple windows instead of a slide door which is more than 12 ft \*\*The approved revised plan shows triple 11-7/8" lvl beam. Have engineer address the installed triple 9.5" lvl beam
- -Fb basement REC room wall space, including space above windows, vertically at ten ft or less interval; Fb wall in basement bedroom closet wall and bathroom wall from ceiling space; Fb basement bedroom 3 wall from ceiling space at top gaps; use 3/4" sheathing for vertical fire blockings

<sup>\*\*</sup>OK TO INSULATE

<sup>\*\*2/22/22-</sup>THIS IS A 2ND FAILED INSPECTION

<sup>\*\*2/25/22-</sup>NOT READY FEE ASSESSED

**Comments:**