## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20212316

Address: 2109 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Michael Harkins Not Ready Friday, February 25,

Residential 2022

Corrective Action Required:

1 Miscellaneous Nail studs at intersecting wall corners per code

Correction (SHEET S1.0 NOTE # 9 2018 IRC TABLE R602.3 (1)

( NOT DONE)

: 2/22/22 NOT DONE CORNER GREAT ROOM NEAR FIREPLACE :

2/23/22 STILL NOT DONE

Provide CS-PF exterior bracing PER PLAN at SGD ( 2018 IRC FIGURE R602.10.6.4 METHOD CS-PF )

: 2/22/22 NOT DONE:

: 2/23/22 NO STRAPS AS SHOWN IN ABOVE FIGURE

**Comments:**