

March 4, 2022

Summit Homes 120 SE 30<sup>th</sup> St. Lee's Summit, MO 64082

RE: Field Issue of floor joist bearing for Lot #101 Manor at Stoney Creek – 4417 SW Tanzanite Circle Lee's Summit, MO 64082 – Permit # PRRES20212071

This letter addresses the floor joist bearing for Lot #101 Manor at Stoney Creek.

- Floor joist is notched for anchor bolt at sill plate and has insufficent bearing area.
- Floor joist spans 14'-10.25" and has standard dead=10 psf and live= 40 psf loads.

## Recommended modifications:

- Install 6' length of Douglas Fir Larch #2 2 x10 sistered to notched floor joist.
- Install 4 fasteners per linear foot in a "W" pattern.

Sincerely,

Bradley Huxol, PE

