CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215762 Address: 504 SE DAVID RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Erosion Control		Michael Harkins	Failed	Wednesday, March 30, 2022
Corrective	Action Required:			
1	DCM1 ESC	EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE		
	REQUIRED NO	PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.		
	FURTHER INSP			
Corrective	Action Required:			
2	DCM6 ESC INSP	STREET CLEAN UP REQUIRED IMMEDIATELY, AND SHALL BE COMPLETED		
	DENIED STREET	PRIOR TO REQUESTED INSPECTION(S) BEING PERFORMED.		
	CLEAN UP			
		MAINTAIN SILT FENCE		
		MAINTAIN GRAVEL FILTER		
		MAINTAIN GUTTER BUDDY	S AT CURB INLETS & REMO	/E SEDIMENT BUILD UP

Comments: