

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20212916
Address: 2366 SW HICKORY LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|---|------------------|----------|-------------------------|
| All Rough Inspection - Residential | Mitchell Schwarz | Failed | Tuesday, April 19, 2022 |

Corrective Action Required:

| | | |
|---|------|---|
| 2 | Misc | -address return air in entry (above blocks) -seal all top and bottom plate penetrations throughout -seal gap between walls at furr out laundry wall and garage wall -fire block to ceiling space dining room NE wall -fire block gaps above fireplace -fireblock chase left of great room back windows -fireblock NE master to attic space -address great room wall to master wall not tied together -address missing LVL in master (2 places) -address wall framing at master W wall under window -seal penetrations/holes in RA panning above Basement bathroom -address over notched joist for dwv in unfinished area west basement wall |
|---|------|---|

Comments: