CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215490

Address: 2812 SW HEARTHSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Wednesday, April 20,

Residential 2022

Corrective Action Required:

2 Misc -install garage doors

-PFH nail pattern

-seal bottom plate penetrations garage entry into kitchen

-furr out for dwv and pex at kitchen S wall and fire block, midway strap dwv

2" in diameter or less

-fire block pantry top plate cut for dwv and pex

-fire block S kitchen wall -see detail s3.2 10 left of slider -secure fireplace in place

-address rafters to top plate in master bedroom -seal top plate penetration in laundry for dwv

Seal gaps

-seal return air panning above beam in basement seal gaps -add stud support under steel beam rear basement wall

Comments: