

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20214555, Public Works Right of Way Permit
Address: 1050 NW INNOVATION PKWY, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Nick Scott	Partial	Tuesday, April 26, 2022

Corrective Action Required

1	Misc	Crews are onsite in the vicinity of the railroad tracks. The crew was informed to contact the Water Department to locate the Sanitary Sewer main near the tracks.
---	------	---

Corrective Action Required

2	Misc	No restoration efforts have been made. Bare ground with clay and rock. No erosion control. This site borders a creek. I left a voicemail with Dennis (Earthworkz) and spoke with Brandon Fossett with UPN. Brandon stated that he would get the area restored ASAP.
---	------	---

Corrective Action Required

3	Misc	Site visited and it appears that grass seed and straw have been put down. Will return in a couple weeks to check on the grass growing
---	------	---

Corrective Action Required

4	Misc	Site visited and grass has not started growing will come back march 1st and check again
---	------	---

Corrective Action Required

5	Misc	Site visited and only 10% of the vegetation has grown back. I will be in contact with Earthworkz to have them come out and do more restoration.
---	------	---

Comments: