CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215181

Address: 2034 SW HOOK FARM DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Thursday, April 28,

Residential 2022

Corrective Action Required:

1 Misc

- -missing nuts on anchors in garage
- -install all windows and doors
- -missing hangers above single car garage
- -address missing studs at rear garage wall
- -furr out and fire block for dwv in garage
- -complete stairs at garage and fire block
- -seal top plate penetration at hvac chase
- -seal penetrations in floor not used for gas
- -security blocking at rear door
- -uncover covered back patio for inspection of rear most beam
- -uncover S3.2 10 at back patio for inspection
- -fire block above fire place
- -front entry wall to be framed to plans
- -uncover covered front porch for inspection
- -block cantilever flex room
- -complete plumbing at tub for bath 2
- -complete bath fans at master
- -address rafters landing on non load bearing wall. Master bath/bed 2 bath
- -strap top plate where lapped less than 24" master/master bath
- -seal floor penetration in jack and Jill bath

-complete bath fan in jack and Jill bath -anchor all steel columns in basement

Comments: