CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20215493Address:2023 SW WHEATFIELD CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Thursday, May 05, 2022
Corrective Action Required:			
1 Misc	 -PFH nailing to plans/code -fire block top of hvac chase seal wall penetrations -seal penetrations in joist space used for RA above mud hall and in panning and REMOVE BLOCKING -cs-pf at rear slider remove trim to view nailing pattern -fire block bed 4 S wall seal gaps -protect NM within 6' of attic access bed 3 closet -vertical to horizontal fireblock if every 10' in basement seal gaps -seal top of furr out walls In basement seal gaps -fire block furr down ends in basement 		

Comments: