CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20220128 Address: 102 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Erosion Control		Inspector:	Outcome:	Date:
		Michael Harkins	Failed	Tuesday, May 10, 2022
Corrective	Action Required:			
1	DCM3 ESC	EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE		
	REQUIRED 2 DAY	WITHIN TWO BUSINESS DAYS.		
		PROVIDE SILT FENCE SOUTH SIDE		
		MAINTAIN SILT FENCE		
Corrective	e Action Required:			
2	DCM3 ESC	EROSION CONTROL REQUI	RED. EROSION CONTROL SH	ALL BE IN COMPLIANCE
	REQUIRED 2 DAY	WITHIN TWO BUSINESS DA	AYS.	
		PROVIDE SILT FENCE SOUTH SIDE OF LOT		
		CLEAN STREET		

Comments: