CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20216391

Address: 2040 SW WHEATFIELD CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Erosion Control Mitchell Schwarz Failed Friday, May 20, 2022

Corrective Action Required:

1 DCM5 ESC INSP REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL

DENIED INSTALLATION.

Corrective Action Required:

2 DCM3 ESC EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE

REQUIRED 2 DAY WITHIN TWO BUSINESS DAYS.

Comments: