CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20216391Address:2040 SW WHEATFIELD CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Erosion Control Mitchell Schwarz Failed Friday, May 20, 2022 Corrective Action Required: REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL 1 DCM5 ESC INSP DENIED REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL Corrective Action Required: REQUISTED INSPECTION. EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANC 2 DCM3 ESC REQUIRED 2 DAY EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANC	Inspecti	on:	Inspector:	Outcome:	Date:
1DCM5 ESC INSP DENIEDREQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION.Corrective Action Required: 2DCM3 ESCEROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANC	Erosion Control		Mitchell Schwarz	Failed	Friday, May 20, 2022
DENIEDINSTALLATION.Corrective Action Required:22DCM3 ESCEROSION CONTROL REQUIRED.EROSION CONTROL SHALL BE IN COMPLIANCE	Correctiv	ve Action Required:			
Corrective Action Required:2DCM3 ESCEROSION CONTROL REQUIRED.EROSION CONTROL SHALL BE IN COMPLIANC	1	DCM5 ESC INSP	REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL		
2 DCM3 ESC EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANC		DENIED	INSTALLATION.		
	Correctiv	ve Action Required:			
REQUIRED 2 DAY WITHIN TWO BUSINESS DAYS.	2	DCM3 ESC	EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE		
		REQUIRED 2 DAY	WITHIN TWO BUSINESS D	AYS.	

Comments: