CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215064

Address: 3713 SW MARYVILLE PL, LEES SUMMIT, MO 640823715 SW MARYVILLE PL, LEES SUMMIT, MO

640823717 SW MARYVILLE PL, LEES SUMMIT, MO 640823711 SW MARYVILLE PL, LEES

SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Patrick Schonfeldt Failed Tuesday, May 24, 2022

Corrective Action Required:

1 Misc UNIT 3717:

- The fire rated wall separating townhouses shall be continuous from foundation to the underside of roof sheathing, fire rating shall extend the

full length of wall or assembly, IRC R302.2.3

NO INSPECTION PERFORMED ON UNITS 3711, 3713, 3715

Comments: