

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20212683
Address: 1033 SW REDBUCK CIR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Shawn Hoffman	Failed	Tuesday, May 24, 2022

Corrective Action Required:

1	Misc	Silt fence on sw side of lot is not intact and large amount of mud has piled into the street. Needs corrected and street cleaned. 4/29/22 ES
---	------	--

Corrective Action Required:

2	Misc	All erosion control needs attention. West side there is no erosion control towards north end of property allowing mud/silt to drain directly into street. Silt socks on SW corner are inadequate for stopping mud/silt from covering ADA ramp or entering roadway. Please correct as this SW corner has previously been addressed and measures are not enough to prevent further issues. 5/24/22 ES
---	------	---

Comments: