CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213817

Address: 3746 SW MARYVILLE PL, LEES SUMMIT, MO 640823744 SW MARYVILLE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Patrick Schonfeldt Failed Wednesday, May 25,

2022

Corrective Action Required:

1 Misc UNIT 3746:

- -No vents or ducts at roof deck within 4' of firewall, see dryer duct
- -provide UL listing and cert for yellow and gray caulk used on firewall
- -seal firewall penetration SE cable basement, this requires UL approved fire

rated intumescent caulk

UNIT 3744:

-No vents or ducts at roof deck within 4' of firewall, see dryer duct -provide UL listing and cert on gray and yellow caulking used on firewall -seal firewall penetration SE cable basement, this requires UL approved fire

rated intumescent caulk

Comments: