

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215871
Address: 2034 SW RED BARN LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Friday, May 27, 2022

Corrective Action Required:

1	Misc	-address rafters landing on blocks though out -address l bracket used for hanger above kitchen next to lvl -seal/fireblock bed 4 to bath wall into furr down(when using Unfaced insulation must be packed tight and secured) -fireblock dead space at wet bar (when using Unfaced insulation must be packed tight and secured) -fire block furred out wall to furr down in bath near wet bar(when using Unfaced insulation must be packed tight and secured)
---	------	--

Comments: