

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20202008
Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Sediment Control (ESC) Inspection	Ronald Paynter	Failed	Monday, June 06, 2022

Informational:

1	Misc	Welch Erosion installed gutter buddies properly on O'Brien, Patch and Killarney. RP 11-10-21
---	------	--

Corrective Action Required:

2	Misc	Curb and field inlets are full of silt and there is excess silt in the roadways. RP 4-4-22
---	------	--

Informational:

3	Misc	ESS had someone come out and clean up the silt in the roadway and curb inlets. RP 4-6-22
---	------	--

Corrective Action Required:

4	Misc	Silt and mud in roadway on O'Brien and cul de sacs of O'Brien and Patch. Need erosion control measures installed and roadways cleaned. 6/6/22 ES
---	------	--

Comments: