

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20210263

Address: 520 NW HOPE LN, Unit:IR, LEES SUMMIT, MO 640811801 NW OBRIEN RD, LEES SUMMIT, MO
64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Robb Popp	Partial	Wednesday, June 08, 2022

Corrective Action Required:

1 Miscellaneous
 Correction

Corrective Action Required:

2 SECOND FLOOR : THE FOLLOWING AREAS ARE APPROVED :

- 2ND FLOOR AREA A
- UNITS 2021,2022,2023,2024,2025,2027,2029,2004,2005,2006,2008

Corrective Action Required:

3 THIRD FLOOR : THE FOLLOWING AREAS ARE APPROVED :

:: 3ND FLOOR AREA A :
3004, 3005, 3006, 3008, 3021,3022,2023,3024,3025,3027,3029

Corrective Action Required:

4 FOURTH FLOOR THE FOLLOWING AREAS ARE APPROVED:

::AREA A:
4004, 4005,4008,4021-4023,4025,4027

4006-MIDPOINT STRAP ALL 2" DWV, SEAL PENETRATIONS, COMPLETE DRAFT
STOP

4024-COMPLETE PLUMBING TO FIFTH FLOOR, STRAP TOP PLATE AT EXTERIOR
WALL PLATE LAP, SEAL FIREBLOCKING AT DEAD SPACE
4029-COMPLETE PLUMBING TO FIFTH FLOOR, STRAP TOP PLATE AT EXTERIOR
WALL, MIDPOINT STRAP 2" DWV, SEAL DRAFT STOP AT SEC

Corrective Action Required:

5 FIFTH FLOOR

Comments: