



June 9, 2022

Kevin Higdon Construction
Attn: Doug Slotter
PO Box 847
Lee's Summit, MO 64063

RE: 807 NE Algonquin St., Lee's Summit, MO 64064

Mr. Slotter,

At your request I have reviewed the as-built condition of the floor joist identified in the recent rough-in inspection summary dated June 7, 2022 specifically relating to the following comment:

- "Provide engineer address for over-notched joist below master bathroom shower"
 - *The as-built condition of the 2"x10" "sistered" floor joist is adequate.*

Should you have any questions please do not hesitate to contact me.

Sincerely,

Kurt Krasick, PE
MAR Building Solutions

1445 SE Broadway | Lee's Summit, MO 64081

Office: 816.272.5435 | Cell: 816.803.3737

kurt@marbuildingsolutions.com | www.marbuildingsolutions.com

