CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20202008

Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Sediment Control (ESC) Ronald Paynter Partial Wednesday, June 15,

Inspection 2022

Informational:

1 Misc Welch Erosion installed gutter buddies properly on O'Brien, Patch and

Killarney. RP 11-10-21

Corrective Action Required:

2 Misc Curb and field inlets are full of silt and there is excess silt in the roadways.

RP 4-4-22

Informational:

3 Misc ESS had someone come out and clean up the silt in the roadway and curb

inlets. RP 4-6-22

Corrective Action Required:

4 Misc Silt and mud in roadway on O'Brien and cul de sacs of O'Brien and Patch.

Need erosion control measures installed and roadways cleaned. 6/6/22 ES

Welch silt fence was onsite putting seed, straw, and silt fence down. 6/7/22

ES

Silt fence is still intact and vegetation is now growing down offsite sewer

line. 6/15/22 ES

Comments: