

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20221111, Public Works Right of Way Permit Address: 302 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Site Visit Inspection Nick Scott Passed Thursday, June 16, 2022

Corrective Action Required

Site visited and it appears work has not started 1 Misc

Corrective Action Required

Misc Site visited and it appears work has started and the road

> crossing on the map from the areal map number 2 street crossing the company got a drill head stuck. The company did a street cut and will be milling out the street and putting new

asphalt. I will come back in a couple weeks to check again.

Corrective Action Required

Street cut still has not been fixed. I will come back in a week to 3 Misc

check again.

Corrective Action Required

Site visited and it appears work is done. The street cut has been Misc

repaired with 2 inches of asphalt capped. Passed

Comments: