CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20210263 Address: 1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Rated Assembly Inspection		Robb Popp	Partial	Friday, June 17, 2022	
Corrective 1	Action Required: THIRD FLOOR	: THE FOLLOWING AREAS A	ARE APPROVED :		
			ND CORRIDOR TO ARRA B CORRIDOR LID TO UNIT 302 AT ROOF DRAINS IN CHASE A	-	
Corrective Action Required:2STAIR TOWER 1Corrective Action Required:3STAIR TOWER 2Corrective Action Required:		: STAIRWAY 1 # 2003			
		: STAIRWAY 2 # 2009 AREA A			
4	SECOND FLOOR	THE FOLLOWING AREAS A	RE APPROVED		
		AREA A			
		-RC CHANNEL AT UNITS AN	ND CORRIDOR TO AREA B		
		-SCREW PATTERN AT COR			
		-SCREW PATTERN AT UNIT AND CORRIDOR TO LOBBY	S 2021,2022,2024,2027,20	29,2004,2005,2006, 2008	
			AT ROOF DRAINS IN CHASE A	T 2008	
Corrective Action Required:					
5	FOURTH FLOOR	: THE FOLLOWING AREAS	ARE APPROVED :		

		 AREA A -RC CHANNEL CORRIDOR CEILING TO FIRE DOORS - -RC CHANNEL AT UNITS: 4004-4006, 4008,4021-4025,4027,4029 - AREA A SCREW PATTERN CORRIDOR CEILING TO FIRE DOORS - -RC CHANNEL Corridor 4007 walls from mechanical closet 4021 to lobby 4011 PROVIDE FIRE COLLARS AT ROOF DRAINS IN CHASE AT 4008 			
Corrective Action Required:					
	liscellaneous orrection	:::FIFTH FLOOR:::			
		:THE FOLLOWING AREAS ARE APPROVED:			
		AREA "A"			
		-RC CHANNEL AT CORRIDOR CEILINGS TO AREA "B"			
		-RC CHANNEL AT UNITS 5004-5006,5008,5021-5025,5027,5029			
		-RC CHANNEL AT CORRIDOR Walls from mechanical closet 5021 to lobby 5011			
		PROVIDE FIRE COLLARS AT ROOF DRAINS IN CHASE AT 5008			
Corrective Action Required:					

7 Misc

Comments: