

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20221458, Public Works Right of Way Permit

Address: 3109 SW BLUE RIBBON ST, LEES SUMMIT, MO 640823113 SW BLUE RIBBON ST, LEES SUMMIT, MO 640823117 SW BLUE RIBBON ST, LEES SUMMIT, MO 640823121 SW BLUE RIBBON ST, LEES SUMMIT, MO 640823125 SW BLUE RIBBON ST, LEES SUMMIT, MO 640823129 SW BLUE RIBBON ST, LEES SUMMIT, MO 640823133 SW BLUE RIBBON ST, LEES SUMMIT, MO 640823130 SW BLUE RIBBON ST, LEES SUMMIT, MO 640823122 SW BLUE RIBBON ST, LEES SUMMIT, MO 640823114 SW BLUE RIBBON ST, LEES SUMMIT, MO 640823106 SW BLUE RIBBON ST, LEES SUMMIT, MO 640822316 SW CHASE CIR, LEES SUMMIT, MO 640822312 SW CHASE CIR, LEES SUMMIT, MO 640822308 SW CHASE CIR, LEES SUMMIT, MO 640822304 SW CHASE CIR, LEES SUMMIT, MO 640822300 SW CHASE CIR, LEES SUMMIT, MO 640822317 SW CHASE CIR, LEES SUMMIT, MO 640823137 SW RAGAN DR, LEES SUMMIT, MO 640823136 SW RAGAN DR, LEES SUMMIT, MO 640823105 SW BLUE RIBBON ST, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Monday, June 20, 2022

Corrective Action Required

1	Misc	Site Visit - The core holes in SW Chase Cir still have not been filled in. I have called the contractor but have not gotten a call back.
---	------	--

Comments: