CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20213431Address:420 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspectio	n:	Inspector:	Outcome:	Date:	
Occupancy Inspection - Engineering		Ronald Paynter	Temporary C of O	Friday, June 24, 2022	
Informati	onal:				
1	Misc	No items to hold up TC corrected:	No items to hold up TCO; however, listed below are items that need to be corrected:		
		1. Storm lid in back parking lot needs replaced with lid that is stamped with "STORM".			
		2. Storm inlet in drive l	. Storm inlet in drive lane needs lifting straps cut out and grouted in.		
		•	uck pond in NE corner of back parking lot needs corrected. h vegetation/landscaping and remove wattles around grass inlets side of building.		

Comments: