# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRRES20220450

Address: 4704 NE POCONO CIR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Thursday, June 30,

Residential 2022

## Corrective Action Required:

1 Misc -Nail the CSPF wall siding to stud/header/rim joist per code; strap the inner

side of portal opening

-Provide full bearing under triple stud at garage/stoop wall

-Nail strap at garage/entry wall intersection

-Double up the attic access trimmer joists. (Access is more than 3ft from

bearing support)

-Strap master bedroom exterior wall to the great room wall

-Seal the return air at master closet wall from roof; do the same for return air

at foyer/closet wall

-Fb floor penetration at trap; Fb wall plate penetrations by ducting

-Strap top plate of hallway wall outside front bedroom to the entry wall

-Provide min 1.5" of bearing for triple IvI beam at stair wall

-Fb basement wall from soffit; Fb basement hallway and bedroom wall from

fur down ceiling space (Fb top gap); Fb wall from joist at bedroom 5 closet

and bathroom

\*\*OK TO INSULATE

### **Comments:**