

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20222793, Public Works Right of Way Permit

Address: 1405 SW GEORGETOWN DR, LEES SUMMIT, MO 640821533 SW GEORGETOWN DR, LEES SUMMIT, MO 640824408 SW LODESTONE DR, LEES SUMMIT, MO 640821705 SW HIGHTOWN DR, LEES SUMMIT, MO 640821809 SW HIGHTOWN DR, LEES SUMMIT, MO 640821901 SW HIGHTOWN DR, LEES SUMMIT, MO 640824402 SW AMETHYST DR, LEES SUMMIT, MO 640824401 SW ALABASTER CIR, LEES SUMMIT, MO 640824420 SW ALABASTER CIR, LEES SUMMIT, MO 640824400 SW ALABASTER CIR, LEES SUMMIT, MO 640824421 SW TANZANITE CIR, LEES SUMMIT, MO 640824400 SW TANZANITE CIR, LEES SUMMIT, MO 640824421 SW GRINDSTONE CIR, LEES SUMMIT, MO 640824400 SW GRINDSTONE CIR, LEES SUMMIT, MO 640821913 SW MERRYMAN DR, LEES SUMMIT, MO 640821937 SW MERRYMAN DR, LEES SUMMIT, MO 640821932 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Wednesday, July 13, 2022

Corrective Action Required

1 Misc

Site Visit - ECC was onsite, they are working on getting the boxes installed today. They should have the boxes installed by today. I spoke with Steve Hult onsite, they will come back it's topsoil to finish off around the boxes. I did remind him about the piles of dirt on the curb, he stated they are trying to not place them on the grass and kill the grass anymore than they need to.

Comments: