CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20210103Address:2100 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Detention Basin		Inspector:	Outcome:	Date:
			Partial	Monday, July 18, 2022
Correctiv	e Action Required:			
1	Miscellaneous Correction		•	d how they still need to get it to it but it has not worked.
Informati	onal:	,		
2	Miscellaneous Correction	3-28-22 AN spoke with Terry again and let him know that we needed the as builts for the structures in the basin and also the basin is still not draining good enough		
Correctiv	e Action Required:			
3	Misc	4-7-22 AN. Spoke with terry and they are making an effort to get the water out of the basin but the rain has made it hard to try and keep it dry.		
Correctiv	e Action Required:			
4	Misc	4-27-22 AN no work pumping water out.	has been done to fix the	e detention basin except for
Correctiv	e Action Required:			
5	Miscellaneous Correction	•	ned. Need to unclog ove led. Excessive amount o	rflow pipe and get silt fence up of silt built up.
		-	ans for correcting the ba	ediment from entering the basin. sin. Their TCO is about to expire I
Informati	onal:			
6	Misc		-	orm box down and they are using e regrading is being done the

basin also needs to be regraded and the riser pipe also needs to be cleaned out. We will also need as graded and as builts

7-15-22 RH. Should be a crew out next week doing rest of the grading. 7-18-22 AN no work on the basin today

Comments: