## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRCOM20213681Address:2150 NW LOWENSTEIN DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Robb Popp	Partial	Friday, July 22, 2022
Informat 1	ional: Misc	-3rd party inspector to verify and document nailing pattern at exterior sheathing		
Corrective Action Required: 2 THIRD FLOOR		-SUPPORT RC CHANNEL AT 2ND FLOOR CORRIDOR WALLS AT EACH END, PROTECT ALL DWV AND DRYER DUCT WITHIN 1.25" OF FACE OF RC CHANNEL-ALL LOCATIONS AREA "A"		
		-RC CHANNEL AT UNITS AN -1ST LAYER AT BATHROOM -SCREW PATTERN AT UNIT	1 WALLS	
Corrective Action Required:		AREA "B" -RC CHANNEL AT UNITS AN -FIRST LAYER AT STAIRWEI	ND CORRIDORS LL UNIT SIDE AND BATHROO	MS
3	SECOND FLOOR	AREA "A" -RC CHANNEL AT UNITS AN -FIRST LAYER AT BATHROC -SCREW PATTERN AT UNIT		'ED
		AREA " B":		

## -RC CHANNEL AT UNITS AND CORRIDORS

Corrective Action Required:				
4	FIRST FLOOR	AREA "A"		
		-RC CHANNEL AT UNITS AND CORRIDORS		
Corrective	e Action Required:			
5	STAIR TOWER 1	STAIR TOWER "A"		

-RC CHANNEL AT CEILING AND THIRD FLOOR LANDING

## **Comments:**