CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20216114

Address: 2202 SW RED BARN LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Monday, July 25, 2022

Residential

Corrective Action Required:

1 Misc

- -complete cspf at ding room missing
- -fireblock master bed furr down into fireplace
- -snow blocking master bed W wall
- -seal top plate penetrations master closet
- -fire block wall space to ceiling space 2nd floor loft walls to ceiling space
- -protect NM with 6' of attic access
- -seal penetrations in 2nd floor hvac room
- -fire block basement bathroom into basement bedroom closet furr down
- -fire block left of basement door into furr down
- -security blocking at basement door
- -anchor bolts through out basement to be within the middle 1/3 of sill plate
- -fire block vertically to horizontally basement family room S wall and E wall
- -fire block basement family room furr out wall to ceiling space
- -fireblock vertical to horizontal every 10' at stairwell

Comments: