CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215797

Address: 2031 SW FARM FIELD LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Monday, August 01,

Residential 2022

Corrective Action Required:

2 Misc

- -nail top plate to header at garage portal frame
- -stud shoe at electrical service cable entry. (Garage W wall)
- -anchor bolt within 12" of plate breaks in garage
- -fire block garage S wall into furr down seal gaps
- -fire block hvac chase into garage furr down
- -address pex through joist over garage entry area/pantry/fridge drilled closer
- than 2'
- -provide collar ties ever 4' over bed 4
- -smoke combo 2nd floor to stay 3' from bathroom
- -vertical to horizontal fire blocking every 10' in basement
- -seal gaps in vertical to horizontal fire blocking

Comments: