

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20220195
Address: 3246 SW ARBORTREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Monday, August 01, 2022

Corrective Action Required:

1 Misc

- address over notched stud near service panel
- miss stud packs at gt bearing points in garage
- cs-of bed 1
- uncover covered patio for inspection (secure all trussed per manufacture specs)
- missing hold down at gt truss above great room windows
- missing hold downs at double truss near slider
- provide attic access above bed 2
- address holes drilled closer than 2" to bottom of floor joist under kitchen island
- address over bored floor joist for dwv near basement window

Comments: