

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20110161, Building Permit - Commercial Address: 1170 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy John Borns Failed Friday, March 25, 2011

Inspection - Codes Commercial

Corrective Action Required

MISC ADDRESS LABELING OF ELECTRICAL SERVICE PANELS --

DESIGNATE WHICH METER SERVES EACH PANEL

Corrective Action Required

2 MISC LABELING OF ELECTRICAL CIRCUITS AT SERVICE PANELS: NEC

408.4; IRC E3606.2. EACH BREAKER MUST BE LABELED. MUST BE LEGIBLE; SPECIFIC. IF PANEL SCHEDULE IS USED NUMBER POSITIONS ON PANEL FRONT PER SCHEDULE. NO DITTO MARKS OR CONTINUATION SYMBOLS EXCEPT @ MULTIPLE

POLE BREAKERS. LABEL UNUSED BREAKERS "SPARE"

Corrective Action Required

3 MISC ADDRESS IDENTIFICATION OF GAS SERVICE ENTRIES: APPLY

PERMANENT TAGS TO LOAD SIDE ENTRY PIPE (NOT ON METER).

Corrective Action Required

4 MISC SOME ELECTRICAL RECEPTACLES AT REAR WALL NOT

SECURED SOLID TO BOX -- TIGHTEN

Corrective Action Required

5 MISC WALL BASE NOT INSTALLED AT SOUTH RESTROOM

Corrective Action Required

Augo

MISC NORTH RESTROOM LACKS HANDICAPPED-ACCESSIBLE SIGN

Corrective Action Required

MISC

7 MISC WATER CLOSETS NOT SEALED TO FLOOR SURFACE

Corrective Action Required

AFFIX "NO SMOKING" SIGN AT EACH ENTRANCE TO BE UTILIZED

BY PUBLIC

Comments: OK TO SET UP FOR BUSINESS. NO PUBLIC UNTIL APPROVED.