CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20221737

Address: 4732 NE FREEHOLD DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Monday, August 15,

Residential 2022

Corrective Action Required:

1 Misc -Nail siding to sill plates per code at front

-Install windows and doors and nail siding per code

-Provide attic access to roof space above garage

-Support valley rafter above garage

-Provide min 2 anchors for garage column

-Over notched joist above garage near I beam

-Fb duct chase from joist space

-Solid block joist ends above bearing wall

-Fb floor at plumbing trap; Fb plumbing space in office from soffit&joist $% \left(1\right) =\left(1\right) \left(1\right) +\left(1\right) \left(1\right) \left(1\right) +\left(1\right) \left(1\right$

space

-Seal gaps along studs of return air space at front 2nd fl bathroom; Fb gap at

top of this double stud wall

-Install hangers at IvI beam connections above hallway bathroom

-Move all roof purlin load off the non-bearing wall

-Above master closet, nail one not-fully-nailed joist hanger and add more

fasteners to 7/16" sheathing to tie rafters to ceiling joists

-Reduce span of hip rafter above master bathroom

-Fb basement bathroom wall from joist

^{**}OK TO INSULATE

Comments: