CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20210775

Address: 1201 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Sediment Control (ESC) Ronald Paynter Partial Monday, August 15,

Inspection 2022

Informational:

1 Misc No erosion issues to report on the job site today. RP 3-23-22

Informational:

2 Misc Another rain day, still no erosion issues to report. RP 3-24-22

Corrective Action Required:

3 Misc Curb and field inlets are full of silt and there is excess silt in the roadways.

RP 4-4-22

Corrective Action Required:

4 Misc Curb inlets are still full of silt. RP 4-8-22

Informational:

5 Misc Curb inlets have been cleaned out. RP 4-11-22

Informational:

6 Misc Welch Erosion was on site installing silt fencing. RP 4-15-22

Informational:

7 Misc Need erosion control installed to prevent dirt and erosion into the yard of

existing house at 2787 SW 11th Terr. Also need erosion control installed around all ADA ramp/sidewalks as mud and silt are building up and washing

into roadways at these locations. 5/24/22 ES

Erosion control measures installed and functioning. 8/8/22 ES

Erosion control measures installed and functioning. 8/15/22 ES

Comments: