# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRRES20216183

Address: 2804 SW HEARTHSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Tuesday, August 23,

Residential 2022

## Corrective Action Required:

1 Misc

- -protect NM with in 6' of attic access
- -snow blocking in dining room
- -provide lateral support for IvI above great room
- -address hole drilled closer than 2" to bottom of joist near basement door and bed room hall entry
- -address over notched joist above basement bath entry
- -fireblock vertically, horizontally every 10' in basement seal gaps
- -address holes drilled through joist above service panel and bed 3 drilled to close to edge and each other
- -fire block into furr down bed 4 closet see beam and dead space to ceiling space
- -water shut off to to remain accessible
- -fireblock S most room
- -seal penetrations in joist space used for RA near S most basement room entry
- -2 (1/2") through bolts at each deck post to beam connection
- -upload engineer letter to permit

### **Comments:**