CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRS	SUBD20200866
---------------	--------------

Address:

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Erosion Sediment Control (ESC) Ryan Heckman Passed Friday, August 26, 2022

Inspection

Informational:

1 Misc Erosion control failed

4.29.2022 Erosion Failed. Muddy roads. No erosion control fencing is in

place. See photos dated 4.29.2022

Corrective Action Required:

2 Misc 8-24-22 RH. Erosion control failed. Inlets are filled with silt and vegetation is

growing out of it. Silt fence is down in multiple places causing silt to run onto road. Inlets need to be cleaned out and silt fence repaired throughout entire

subdivision.

8-26-22 RH. Inlets were all cleaned out and silt and vegetation was removed.

Comments: