

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215682
Address: 4405 SW GRINDSTONE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Failed	Tuesday, August 30, 2022

Corrective Action Required:

1	Misc	-fire block hvac chase into furr down (not complete) -hanger for beam above front stoop (cannot inspect with cover, remove fascia to see beam bearing end) -gt bearing and hold downs bed 4 closet (not complete) -address joist above kitchen drilled for pex holes closer than 2" -address over drilled joist near egress window in basement (PROVIDE ENGINEER LETTER FOR FIELD FIX WITH STRAP) -address holes in floor joist drilled to close together near egress window (BORES LESS THAN 2" APART)
---	------	--

Comments: